



## Institute for Social and Economic Change

Dr. V.K.R.V. Rao Road, Nagarabhavi P.O., Bengaluru – 560 072

[www.isec.ac.in](http://www.isec.ac.in)

### Inviting quotes for demolition of first floor of coffee lounge in the ISEC Campus

|     |                                  |   |   |
|-----|----------------------------------|---|---|
| 1.  | Name of the tender/quotation     | : | Demolition of coffee lounge in the first floor at ISEC  |
| 2.  | Area to be demolished            | : | 51'8" X 31'3"   |
| 3.  | Type of structures               | : | Column's, beams, slab, walls, doors, and windows  |
| 4.  | Tools and machineries to be used | : | Concrete cutters, fork lifters, cranes, hydraulic / mechanical machineries or tools   |
| 5.  | Caution                          | : | Extra care to be taken to avoid any impact to the ground floor and adjoining buildings. Avoid damage to the vitrified tiles. Avoid dust or other flying particles by pouring of water and covering the building with plastic sheets / safety net, etc.  |
| 6.  | Disposal of debris               | : | Debris/demolished concretes are to be removed from the ISEC campus at your cost.  |
| 7.  | Slab sections                    | : | Slab sections to be cut at a size of 2' x 3' and handed over to ISEC  |
| 8.  | Window panes                     | : | Property of ISEC  |
| 9.  | Wooden doors                     | : | Property of ISEC  |
| 10. | Submission of tender/quotation   | : | <ul style="list-style-type: none"><li>➤ Last date: <b>18<sup>th</sup> May 2018</b></li><li>➤ Tender/Quotation should be submitted in a closed cover superscribing "<b>Quotation for demolition of first floor of coffee lounge in the ISEC Campus</b>" and addressed to <b>The Registrar, Institute for Social and Economic Change, Dr. V.K.R.V. Rao Road, Nagarabhavi P.O., Bengaluru – 560 072.</b></li></ul> |

#### Notes:

- (a) *Before quoting you can visit the site for any clarifications from Estate Office on working days between 10 am and 5 pm.*
- (b) *The manpower employed by the contractor should be covered under insurance. ISEC will not be responsible to any unknown incident(s).*

Registrar